## X Flex Installation Instructions

If charging is required, install the charge cable at the tablet first [refer Sprocket tablet installation guide]

M4 Washer

M4X50 Socket Head Screws

Use M3 Allen Wrench to tighten

If needed, drill a 5/8" [16mm] hole in the center, so that the USB cable can pass through the surface.


\_\_\_\_\_4mm (1/6") wood bit

M4 Nut

1111

깜팡깜

4




🗕 Ø 75.0 🗖

Left View

3.0

Front View

**4** sprocket



Installation & Assembly Guide

X Flex

Find more information, warranty details and instructional videos at www.sprocket.com.au

2024 Sprocket Pty Ltd. All Rights Reserved.